


COFC



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of: Prindiville et al.

Date Mailed January 12, 2006

Patent No. 6,891,108

Issued: May 10, 2005

Application No. 09/971,985

Filed: October 4, 2001

Confirmation No. 4109

For: SEMICONDUCTOR PACKAGES AND
METHODS FOR MAKING THE SAME

Examiner: Jeremy C. Norris

Art Unit: 2841

Attorney Reference No. 6047-61246-01

Certificate
JAN 20 2006
of Correction

COMMISSIONER FOR PATENTS
P.O. BOX 1450
ALEXANDRIA, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

The following errors were noted in the printed patent:

Cover Page:

Column 1, under "References Cited," add the following references (which were
acknowledged by the Examiner on 10/17/03):

| | | |
|-----------|---------|-------------------|
| 5,475,918 | 12/1995 | Kubota et al |
| 5,696,033 | 12/1997 | Kinsman, |
| 5,715,143 | 2/1998 | McHugh et al |
| 5,789,803 | 8/1988 | Kinsman |
| 5,952,611 | 9/1999 | Eng et al. |
| 5,953,216 | 9/1999 | Farnsworth et al. |
| 5,998,860 | 12/1999 | Chan et al |
| 6,013,535 | 1/2000 | Moden et al. |
| 6,017,776 | 1/2000 | Jiang et al. |
| 6,021,563 | 2/2000 | Heo et al. |
| 6,023,666 | 2/2000 | Jiang et al. |
| 6,048,755 | 4/2000 | Jiang et al. |
| 6,060,339 | 5/2000 | Akram et al. |
| 6,084,311 | 7/2000 | Jiang et al. |

JAN 31 2006

01/17/2006 HUONG1 00000080 6891108
01 FC:1811 100.00 DP

| | | |
|-----------|---------|------------------|
| 6,091,136 | 7/2000 | Jiang et al. |
| 6,091,140 | 7/2000 | Toh et al. |
| 6,098,278 | 8/2000 | Vindasius et al. |
| 6,110,805 | 8/2000 | Schrock et al. |
| 6,111,324 | 8/2000 | Sheppard et al. |
| 6,201,299 | 3/2001 | Tao et al. |
| 6,218,731 | 4/2001 | Huang et al. |
| 6,265,766 | 7/2001 | Moden |
| 6,303,997 | 10/2001 | Lee |
| 6,326,700 | 12/2001 | Bai et al. |
| 6,331,451 | 12/2001 | Fusaro et al. |

In the Specification:

Column 4, line 67, "convention slot widths" should be --conventional slot widths-- (application, page 7, line 29).

Column 5, line 34, "opening (see" should be --opening) (see-- (application, page 8, line 24).

Column 5, line 51, "operational die" should be --operational dies-- (application, page 9, line 7).

Column 6, line 5, "die sites" should be --die sites)-- (application, page 9, line 25).

Column 6, line 27, "functional dies sites" should be --functional die sites-- (application, page 10, line 12).


A Certificate of Correction is enclosed to make formal notice of the errors in the referenced patent. Our check in the amount of \$100.00 is enclosed.

Please return the enclosed postcard to confirm that these documents have been received.

Respectfully submitted,

One World Trade Center, Suite 1600
121 S.W. Salmon Street
Portland, Oregon 97204
Telephone: (503) 595-5300
Facsimile: (503) 595-5301
cc: Client
Docketing

KLARQUIST SPARKMAN, LLP

By 
Donald L. Stephens Jr.
Registration No. 34,022

JAN 31 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,891,108

DATED : May 10, 2005

INVENTOR(S) : Prindiville et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Cover Page, References Cited

| | | |
|-----------|---------|-------------------|
| 5,475,918 | 12/1995 | Kubota et al |
| 5,696,033 | 12/1997 | Kinsman, |
| 5,715,143 | 2/1998 | McHugh et al |
| 5,789,803 | 8/1988 | Kinsman |
| 5,952,611 | 9/1999 | Eng et al. |
| 5,953,216 | 9/1999 | Farnsworth et al. |
| 5,998,860 | 12/1999 | Chan et al |
| 6,013,535 | 1/2000 | Moden et al. |
| 6,017,776 | 1/2000 | Jiang et al. |
| 6,021,563 | 2/2000 | Heo et al. |
| 6,023,666 | 2/2000 | Jiang et al. |
| 6,048,755 | 4/2000 | Jiang et al. |
| 6,060,339 | 5/2000 | Akram et al. |
| 6,084,311 | 7/2000 | Jiang et al. |
| 6,091,136 | 7/2000 | Jiang et al. |
| 6,091,140 | 7/2000 | Toh et al. |
| 6,098,278 | 8/2000 | Vindasius et al. |
| 6,110,805 | 8/2000 | Schrock et al. |
| 6,111,324 | 8/2000 | Sheppard et al. |
| 6,201,299 | 3/2001 | Tao et al. |
| 6,218,731 | 4/2001 | Huang et al. |
| 6,265,766 | 7/2001 | Moden |
| 6,303,997 | 10/2001 | Lee |
| 6,326,700 | 12/2001 | Bai et al. |
| 6,331,451 | 12/2001 | Fusaro et al. |

Column 4,

Line 67, "convention slot widths" should be --conventional slot widths--.

Column 5,

Line 34, "opening (see" should be --opening) (see--.

Line 51, "operational die" should be --operational dies--.

Column 6,

Line 5, "die sites" should be --die sites)--.

Line 27, "functional dies sites" should be --functional die sites--.

MAILING ADDRESS OF SENDER:

Klarquist Sparkman, LLP
One World Trade Center, Suite 1600
121 SW Salmon Street
Portland, Oregon 97204

PATENT NO. 6,891,108

No. of add'l copies _____
(@ .30 per page)